



# ZP-02



Widely used at home, medical institutions, community centers etc.



Accurately measures  $SPO_2$  and Pulse Rate



Low Battery Indicator




Automatic Power Off when there is no signal



Ideal for Trekkers



Temperature  
-10°C ~ +50°C



Atmospheric pressure  
50kPa ~ 106kPa

## SPECIFICATIONS

SPO <sub>2</sub> :	Measurement range: 35-100% Resolution: 1% Accuracy: 70% - 100%, +2%
Pulse rate:	Measurement range: 25-250 bpm Resolution: 1 bpm Accuracy: +2 bpm
Power:	Two AAA alkaline batteries
Environment:	Operation Temp : 5 to 40oC Storage Temp : -10 to 50oC
Humidity:	Operation: 15 to 80% Storage: 10 to 93%



# 2